

1501 West 178th Street | Gardena, CA. 90248 310-767-7812 | 800-359-5679 | fax: 310-767-7836 <u>info@matsui-color.com</u> | <u>www.matsui-color.com</u>

WS0501 Stretch Clear 301

Technical Data Sheet

- Wet Ink Tack | Low
- After Flash Tack | Low
- Printability | Excellent
- Surface Appearance | Matte
- **Opacity/Viscosity** | Low/Low
- Bleed Resistance | None
- Flash Temperature | 160°F (71°C)/decreases with deposit thickness
- Cure Temperature | 320°F (160°C)
- Squeegee Hardness |
 Medium
- Squeegee Blade | Sharp
- Squeegee Angle | 45 degrees to screen
- Squeegee Speed | Medium
- Underlay | 301 Series
- Emulsion | Direct or indirect
- Mesh Count | 86-160 mc in (34-63 mc cm)
- Thinner | RV Additive
- Thickener | Thickener B
- **Storage** | 65°F to 95°F (18°C to 35°C). Avoid direct sun.
- Cleanup | Water and mild soap or detergent
- Color Range | Clear
- Substrate Type | Cotton
- Substrate Color(s) | Light and Medium Fabrics

Description

Stretch Clear 301 is a clear mixing base for "**Performance**" and high stretch fabrics that can be mixed with "**Neo Pigments**" to achieve an extremely soft hand feel and excellent elasticity. This product has a translucent appearance.

Features

- Easy to mix and print
- Creates thousands of color shades by adding up to 15% Neo Pigments
- Excellent printability with no viscosity modifications
- Extremely soft hand feel that PVC inks cannot achieve
- Excellent elasticity, great on Dri-fit performance fabrics
- Creates tone on tone look with superb softness
- OEKO-TEX[®] Standard 100 certified, CPSIA and HR4040 Compliant
- Is "PVC Free" and environmentally safe

Application

Print through fine screen mesh up to 160 mc in (63 mc cm) when cured at 320°F (160°C), **Stretch Clear 301** produces the softest prints achievable in textile screen printing today.

Special Recommendations

<u>Stretch Clear 301 should be mixed in clean vessels using clean mixing blades and</u> utensils. Any contamination from other ink sources or non-approved additives could make **Stretch Clear 301** test positive for restricted PVC's.

- Stretch Clear 301 can be dry cleaned or ironed
- Use Retarder MG 1-5% to help with open time in the screen
- Use Fixer WF-N 1-5% to help with wash fastness
- Use Softener MG 1-4% to help penetrate in to the garment
- Use Thickener B .25-1% to help thicken the ink
- Use RV Additive 1-3% to reduce viscosity